Nº 5799

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-8-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	6º dech
WAS LATERAL AT CURBI	and the second of the second o	•
WAS ATTACHED TO MAIN Yes SHOW BY DIAGRAM RELATION OF LATE	NAME OF CONTRACTOR REMISELY	
27 Tet 57		5 Tide
Agus e e e e e e e e e e e e e e e e e e e	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	40/4
SIGNED John Lingsector for Cit	endition if or surjourned principle de distri	5//8/52

## Nº 5799

## PERMIT TO TAP SEWER

RECEIVED OF Rendey	FEE OF \$ 2.0
FOR WHICH PERMISSION IS GRANTED	•
0	
the state of the s	R, ON THE CASE AND
OF 2 7 th St. TYP	E OF STREET DINT
THE PREMISES BEING LOT NO. 69 / 2	, HOUSE NO. 3 2 3

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.