

Nº 5801

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-8-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1837

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 51' 6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lindbergh Ave. N.E.



SIGNED

John E. Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5/10/52

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5801

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5-7 1915RECEIVED OF Diana FEE OF \$ 2.0FOR WHICH PERMISSION IS GRANTED Rudy RossTO TAP Sanitary SEWER, ON THE SouthOF Lendbergh NE AVE., TYPE OF STREET Black Top
ST.,THE PREMISES BEING LOT NO. Plat 9115 + 9116, HOUSE NO. 1837WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR Diana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.