FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-13-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 8/5		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE CORRESPONDED TO STREAM TO DITCH AT CURB LINE AND DEPTH	7' doch
WAS LATERAL AT CURBA Y C 7	The state of the s	·
WAS ATTACHED TO MAIN 425	NAME OF CONTRACTOR Diama	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
16 TH ST, N.	. E	
	7 'd coff or free man	
alente in matalanti. La la come para interpreta del	· · · · · · · · · · · · · · · · · · ·	
	victorial bush of he share for his results of	
		61.
en e		
1 may a series of a	10	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	
	osilised to stopping at public to altern	0/1/106
REMARKS:		

, which ${f N}_{2}^{o}$ at 5803 we consider ${f N}_{2}^{o}$

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

and the second of the second o
MASSILLON, OHIO, 15
RECEIVED OF a Alana FEE OF 5 25
// FEE OF 3
The Contract of the Contract o
FOR WHICH PERMISSION IS GRANTED
TO TAP SEWER, ON THE
OF 16-th 20 6 AVE. TYPE OF STREET Famed.
THE PREMISES BEING LOT NO. 5896 , HOUSE NO. 83
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
- Para Para Para Para Para Para Para Par

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.