FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 47 SIZE OF PIPE USED 4 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH WAS LATERAL AT CURB7 WAS ATTACHED TO MAIN NAME OF CONTRACTOR REPORT AND LAY	
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH WAS LATERAL AT CURB7	
,	
WAS ATTACHED TO MAIN	
NAME OF CONTRACTOR _ Z / C / / / Z /	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
3 RD 5T 5 W	
one of the control of	R
	4 ,
0 168	77.
SIGNED John Charles FILED AT ENGINEER'S OFFICE	Tale States
REMARKS: Relaid 106,	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

and the second of the second o
MASSILLON, OHIO, 19
RECEIVED OF FEE OF \$
FOR WHICH PERMISSION IS GRANTED hammed down
TO TAP Sanctary SEWER, ON THE West
OF 3 rd At M. AVE. TYPE OF STREET Parish
THE PREMISES BEING LOT NO. 169, HOUSE NO. 47
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.