

Nº 5810

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.


DATE INSPECTED 6-12-52IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 819SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH182'7'WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Diana(Joe + Joe
Canton)

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. F. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-27-52

REMARKS:

Joe + Joe, Canton Contr did this work under Diana permit.

Nº 5810

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/11 1920

RECEIVED OF G. L. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Bessie Spuhler

TO TAP San

SEWER, ON THE S.

OF Bennington NE AVE. TYPE OF STREET Alled

THE PREMISES BEING LOT NO. 8533 6 of 8532 HOUSE NO. 819

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.