Nº 5812 AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-7-52 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	# # # # # # # # # # # # # # # # # # #
HOUSE NO. 1339	
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE CURB LINE AND DEPTH	dech
WAS LATERAL AT CURB? Yes	• /
WAS ATTACHED TO MAIN VES NAME OF CONTRACTOR DIAMA	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	6
Lennox Ave N.E.	
g's ash	
	. \
and the first of the analysis of the Alexandra (1997) and the contract of the	911
THE COUNTY OF THE PROPERTY OF	8
Management and Company to the Company to the Company of the Compan	entransia di Persona di Amerika d
SIGNED John Engineer'S OFFICE 6	
INSPECTOR FOR CITY IN PLACE THE PROPERTY OF T	and the same of th
REMARKS:	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5812

PERMIT TO TAP SEWER

ander promite (An Land to An La	Massillon, Ohio,	6-12
RECEIVED OF Deance		FEE OF S 2.1
FOR WHICH PERMISSION IS GRANTED Mule (Chard	
TO TAP Sanitary SEWER.	ON THE SOU	th
OF Lennox It. E AVE. TYPE	of street bu	ick
THE PREMISES BEING LOT NO. 8772	, HOUSE NO,	133 9
Work to be done in accordance with Ordinance Rules of the Department of Public Service.	No. 2323, DULY PA	SSED BY THE CITY COUNCI
NAME OF CONTRACTOR Diana	·	

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.