

Nº 5817

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-11-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 42

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 151 7'6" deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

22' NB ST. N.W.

← N

6' deep

9' deep

12

5

151

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6/20/52

REMARKS: _____

Nº 5817

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/11/19

RECEIVED OF

Geo Hasler

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Remley

TO TAP

San

SEWER, ON THE

east

OF

22nd N W

AVE.,

TYPE OF STREET

hard surface

THE PREMISES BEING LOT NO.

7746 + 7747

HOUSE NO.

42

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.