

14-27

Nº 5821

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-26-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

216'

10' deep

HOUSE NO. _____

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Rogers.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Singing Brook Dr.



SIGNED

John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-2-52

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5821

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/25/52 19RECEIVED OF Dale RogersFEE OF \$ 5.0FOR WHICH PERMISSION IS GRANTED Albert V. CalucciTO TAP Sanitary

SEWER, ON THE

OF Singing Brook Dr.AVE.
ST.

TYPE OF STREET

CinderTHE PREMISES BEING LOT NO. 17-BrooksideHOUSE NO. Acres

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Dale Rogers

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.