N^o 5822 And signed when returned.

DATE INSPECTED 7-11-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 820		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	6 deep
WAS LATERAL AT CURBY YES	n og kommune i flere i kommende er	sandrani (1920) ya masali ili kata ili Kata ili kata ili ka
WAS ATTACHED TO MAIN Ves	NAME OF CONTRACTOR	ey .
SHOW BY DIAGRAM RELATION OF LATE		
Taylor Ave		
Carrier to the property of the	ាំង ចំនៅក្នុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប ក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្រុងប្រជាពិក្	######################################
		3/16de-138 3
1 1 01		6
SIGNED The Color FOR CO	FILED AT ENGINEER'S O	وروها والهلا الهي المستوع النبي التهي التهي
REMARKS:	i apidee.M criteridae of galblind to	2 16 5 5 7

Nº 5822

PERMIT TO TAP SEWER

<u> </u>	Massillon, Ohio, Gunt 26
d	RECEIVED OF Bangoen Penard FEE OF \$ 2.1
	FOR WHICH PERMISSION IS GRANTED
ul mino	TO TAP Soundary SEWER, ON THE LOUST
June	OF Toylor & W AVE. TYPE OF STREET ANIA Sunface
i i i i i i i i i i i i i i i i i i i	THE PREMISES BEING LOT NO. 46/7, HOUSE NO. 820
	Work to be done in accordance with Ordinance No. 2323, Duly passed by the City Counci Rules of the Department of Public Service.
	P a Day
	NAME OF CONTRACTOR TENNILLY

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.