FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

and the second s		
DATE INSPECTED 1-10-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1024		,
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	62 Deep
WAS LATERAL AT CURBY Yes .	The second of th	
	NAME OF CONTRACTOR BOGEY	
SHOW BY DIAGRAM RELATION OF LATE		
on produce produce in the second control of the second control of the second control of the second control of Marian Control of the second control of the	$N = \frac{1}{15\sqrt{2}}$	·
		-920C12
elikaj li maj li li kiologo on kiologo o n delikaj li kiologo. Li li		
	62 Deep	132 CE. Curb
		Main Sewer
OF I	172'	·
SIGNED 1 U' WOULL	FILED AT ENGINEER'S OFFICE	8/19/52
INSPECTOR FOR CITY	Caraffeed? Fed to daine si publicina to allow	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR AND MARCH

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.