

Nº 5825

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-25-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 225

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

22'

4' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

OHIO AVE. N.E.



SIGNED

John Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/15/52

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5825

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/10 1920RECEIVED OF W. H. Harris FEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED SameTO TAP San SEWER, ON THE DOF Ohio St. E. AVE., TYPE OF STREET Hard surfaceTHE PREMISES BEING LOT NO. 5501 HOUSE NO. 225WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR Diana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.