## Nº 5832

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-5-52	IF SO HOW AND LOCATION FROM Y 269'
HOUSE NO. 444	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	The Control of the Co
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR L. Albrecht
SHOW BY DIAGRAM RELATION OF LATER	
	3'deep
evalundo o promoto en enconero dos allabados de la	Main
	Ste 1
	Q 269, 13/8, dup 6 21
SIGNED LINY Latter	FILED AT ENGINEER'S OFFICE 9 29-53
PEMARKS	na literation de surgidas de philiphia de allem

## Nº 583

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	たらない server or index 数数の George of the Media を見る Giornia of Liberta 数字ではい	Massillon, Ohio,	July 30
RECEIVED OF GSI	지수가 그 그 시작하다 하다.		FEE OF <b>5 2.</b> 0
FOR WHICH PERMISSION IS G	RANTED 88MC		
TO TAP Senitary		a productive services and the services of the	
			· · · · · · · · · · · · · · · · · · ·
THE PREMISES BEING LOT NO.		, HOUSE NO, _	4.4 6.4 自己 医二氏管囊膜皮肤管囊
WORK TO BE DONE IN ACCO	RDANCE WITH ORDINAN	CE NO. 2323, DULY PA	SEED BY THE CITY COUNC
RULES OF THE DEPARTMENT C	OF PUBLIC SERVICE.		

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.