Nº 5834

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

•	
DATE INSPECTED 8-5-5-2	IF SO HOW AND LOCATION FROM Y'' 205
HOUSE NO. 45-4	ZIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI NO	 A Section 1997 And the second of the second o
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR L. Albrecht
SHOW BY DIAGRAM RELATION OF LATE	
ili. National de la companya de la compa	(N) /3' deep
Halika kan ang mga mga mga mga mga mga mga mga mga mg	Main
	124'1 8' deep 40
	203
SIGNED ALLAY JOILEN INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 9-28-53
REMARKS:	e nestje vilke er opsteles ni gedistret in diese.

Nº 5834

PERMIT TO TAP SEWER

	en e	ssillon, Ohio,	Jyly 30
FOR WHICH PERMISSION IS GRA	on Paige Constr NTED <u>Same</u>		
TO TAP Senitery	SEWER, ON	THE BAST	
of Carver NW	AVE., TYPE OF	STREET Dirt	
THE PREMISES BEING LOT NO.			
WORK TO BE DONE IN ACCORD	ANCE WITH ORDINANCE NO	D. 2323, DULY PA	SSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF	PUBLIC SERVICE.		

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.