$N^{\circ}$  5869

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED _/U-27-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  //5
HOUSE NO. 464	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE TO DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	. Tarif in
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR L. Albrecht
SHOW BY DIAGRAM RELATION OF LATER	
	This can be seen to be
t 1868. And fra the explored again the	N de train de la martina de la companya de la compa
	15 C'del
SIGNED LYOY Lother	FILED AT ENGINEER'S OFFICE 12-23-53
/ INSECTOR FOR CIT	acilianski er trojém zi pribliné in ziřav j

## Nº 5869

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER 1

불리 경험 등 이 사람은 이를 하지만 작은 동안에 보는 것		Massillon, Ohi		
RECEIVED OF	si ci pi sialam ausoc Malia dua ausoca		ori ony e	EE of \$ 2.7
TO TAP Senitary			East Dirt	
OF Standion NW THE PREMISES BEING LOT NO. 1		E OF STREET, HOUSE		

NAME OF CONTRACTOR L. ALDROCAL

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.