FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N^{o} 5873 AND SIGNED WHEN RETURNED.

	- m
DATE INSPECTED	FIRST MANHOLE DOWN STREAM
HOUSE NO. 486	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE CONTROL OF THE CONTROL OF T
WAS LATERAL AT CURB?	O
WAS ATTACHED TO MAIN YE	5 NAME OF CONTRACTOR L. Albrecht
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.
	N 3 dup
erate epita lisar en alles en ella el 1898	CON HERMANDER BOOK OF THE CONTROL OF
	Love case the wife and transmarked the no require
9	
SIGNED AND AND AND AND AND AND AND AND AND AN	FILED AT ENGINEER'S OFFICE 12-22-53
o ja en Holingo Nafikusii ka k	ក្រុង 👯 ការដែលខេត្ត (a) សក្សន៍សមាន ក្នុងស៊ីស៊ីសតិ នៃ សំរីស្តេ 🧸 -
REMARKS:	

$\mathbf{N}_{\cdot}^{\mathbf{o}}$ 5873

PERMIT TO TAP SEWER

AND THE REPORT OF THE PROPERTY	SSILLON, OHIO, JULY 30
불빛물리가 있는 사이는 가끔없는 것이 없는 것이다.	
RECEIVED OF GATEON Price Construct	tion Company FEE of \$ 2.
FOR WHICH PERMISSION IS GRANTED 5736	
TO TAP SEMER, ON T	HE Sast
OF '다는 경기에 'AVE.' TYPE OF '	STREET TITL
Andrew State of the Control of the C	
THE PREMISES BEING LOT NO. 17015	, HOUSE NO. 486
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	. 2323, DULY PASSED BY THE CITY COUNC
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.