Nº 5883

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

| DATE INSPECTED 10-29-5 | 2 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 93 |
|--|--|
| HOUSE NO. 461 | |
| SIZE OF PIPE USED | DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? NO | and the Marian and the second control of the second control of the second control of the second control of the |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR L. Albrecht |
| SHOW BY DIAGRAM RELATION OF LA | ATERAL TO WALL OF BUILDING SERVED. |
| o de la composição de la Composição de la composição de la composiç | |
| | and the contract of the contra |
| | 3idus |
| Property of the property of the second of th | |
| | 181 4' del |
| SIGNED Livory Gal | Harn FILED AT ENGINEER'S OFFICE 17-23-53 |
| /NSPECTOR FOR | i CITY |

Nº --5883

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

| en de la companya de La companya de la co | rein som ekstin Voktoren da ett | MASSILLON, C | Н10, | July 3 | <u>30</u> | 1! |
|--|--|-------------------|--------|--------|-----------|-------|
| Received of Garson F | ei se Con | stanction | Com | anv . | | 2.00 |
| FOR WHICH PERMISSION IS GRANTED | an da es ta de altera. Decemberation | | | | | |
| TO TAP SEN 115TY | | ON THE | | West | | 3 ¥7 |
| The state of the s | dakwa kua: | er dagenda å fyrs | Natest | | | |
| THE PREMISES BEING LOT NO. 71025 | | , ноп | | 461 | | |
| WORK TO BE DONE IN ACCORDANCE W | | | | . – | IF CITY | COUNC |
| RULES OF THE DEPARTMENT OF PUBLIC | | | 1. | | | |
| Name of Contractor L. Al | Lbrecht | | | | | |

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.