N 9 5890

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-23-5-2	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 6707	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	i kanana da 19 <u>18. Izaba</u> baran kanana kanan kanan kanan da apate pang
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR LIAIbrecht
SHOW BY DIAGRAM RELATION OF LATE	
our and Selection (المنظم المنظم المنظم المنظم المنظم	
s proposition of the contract	HOLD THE REPORT OF THE BANK BLIND OF THE BOTTON
•	
	0000 17.13,5 desp
	232'
SIGNED ALLOY LOLL	FILED AT ENGINEER'S OFFICE 12-23-53
MSPECTOR FOR C	Northeada at National Englished In they
REMARKS:	

Nº 5890

PERMIT TO TAP SEWER

		no, servis d <mark>ass</mark> e a l a a cho est <mark>ino</mark> na c esti di	Massillon	, Оню,	July 3	0_1
RECEIVED OF	Garson Pai	ge Const	ricion	Company	FEE OF	<u>. 2.0</u>
FOR WHICH PERMISSI	ON IS GRANTED	Sene			i nerelettiget.	
_{to tap} Santiar		1	ON THE	West		
or Standish	MM	AVE. TYPE	OF STREET	Dirt		
THE PREMISES BEING I		3 * • • •		DUSE NO		
WORK TO BE DONE I	N ACCORDANCE WIT	TH OPDINANCE				
RULES OF THE DEPAR			- 110. 2323	, DULI PASSE	U BY THE CITY	COUNC
NAME OF CONTRACTO		brecht				

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.