

Nº 5911

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-5-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 800

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 117' 8" deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Roger

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

17th ST. N.E.

N



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/19/52

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5911

PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept 4

RECEIVED OF

Dwain R. Roger

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

1111 Pleasant

TO TAP

Sanitary

SEWER, ON THE

North

OF

17thAVE.,
ST.,

TYPE OF STREET

Land surface

THE PREMISES BEING LOT NO.

801648011

, HOUSE NO.

800

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Dwain R. Roger

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.