Nº 5913

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED $9-16$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 1725			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8'	Deep
WAS LATERAL AT CURB7	Yesona montational consists as a second	ALBERTANIAN TOTAL	
	NAME OF CONTRACTOR 60	ger	
SHOW BY DIAGRAM RELATI	ON OF LATERAL TO WALL OF BUILDING SERVE	D.	
	Total A.C. (2004) (2004) (2004) (2004) (2004) (2004) (2004)	14/2222)ccP
	The control of the co	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	L' Dee,	/,	Curb Line
0 = 0	1 79'		Main Dewi
SIGNED NOSP	ECTOR FOR CITY FILED AT ENGINE		123/52
ong kalaga Midisa d	Popularity a thronic of residence and a	ied îv rîtovi	

OFFICE OF THE DIRECTOR OF PUBLIC SERVIC PERMIT TO TAP SEWER

	កាលប្រជាពល់កាលប្រកាសប្រ ពេលប្រាប់ក្រុម ប្រជាពល់ការបានប្រ	MASSILLON,	OHIO, Sept /	<u> </u>
RECEIVED OF	Discus-	Bogin	FEE (DF 5 2.1
		weete	ruderback	James .
FOR WHICH PERMISSION	I IS GRANTED 17		- angle	1 - 1
TO TAP Sanua	<u>w</u>	SEWER, ON THE	west	*:
of Windson	THE AVE	TYPE OF STREET	orled	THE THE PART OF TH
THE PREMISES BEING LO			DUSE NO. 172 S	<u> </u>
		•	DULY PASSED BY THE C	TTV COUNT
TOTAL TO BE BOILE IN		B	DOL. TASSED BY THE C	III COUNT

This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.