

Nº 5914

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-23-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 816

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 153' 7' deep



WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Hamm

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED:

Milburn Ave N.E.



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10/23/52

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 5914 PERMIT TO TAP SEWER

MASSILLON, OHIO, 9-23-1972

RECEIVED OF A. G. Linking FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED A. G. Linking

TO TAP Sanitary SEWER, ON THE north

OF Melburn NE AVE., TYPE OF STREET oil & gravel

THE PREMISES BEING LOT NO. 8055 HOUSE NO. 816

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Paul Hagan

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.