

Nº 5921

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-22-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 921 Rear

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

42' 7' deep



WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Amhurst Rd. NE



SIGNED John E. Shover
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10/23/52

REMARKS: Built M.H. on Lateral To house in front.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº 5921 PERMIT TO TAP SEWER

MASSILLON, OHIO, 10-10-

RECEIVED OF

R J Liana

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Maurice A. Liana

TO TAP

Sanitary

SEWER, ON THE

West

OF

Ambert N E

AVE.,
ST.,

TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

6988

HOUSE NO.

Rear 921

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R J Liana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.