Nº 5922

REMARKS:

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-3-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 789 - 4'6'6-4
WAS LATERAL AT CURBY 1460	and the second section of the second
WAS ATTACHED TO MAIN 149	NAME OF CONTRACTOR Diana
SHOW BY DIAGRAM RELATION OF LATER	
STONER	RD, NE
	. The second of
o karangan sa karangan sa pangan karangan karangan sa pangan sa pangan sa pangan sa pangan sa pangan sa pangan Bangan	= the property of the policy o
THE STATE OF THE S	189 4.6.6.
	0
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 10/2.5/32

Nº 5922

PERMIT TO TAP SEWER

			Massili	LON, OHIO, 10	-10	· · : :: · · · · · · · · · · · · · · ·
RECEIVED OF	2009	20 0	wer		FEE OF	ş 9.
FOR WHICH PERMISS	ION IS GRANT	ED 0,7,7		Erole		7 1/3
1.	T.	$\mathcal{J}_{\underline{}}$		Ch m	7.A	
OF COMMENT	7 5	n an Guillean an a	WER, ON THE_	et du	7	281
THE PREMISES BEING	LOT NO. F		t=7	., HOUSE NO	1812	
WORK TO BE DONE			ANCE No. 23	123, DULY PAS	SED BY THE CITY	у Сопис
NAME OF CONTRACTO	DR C	Dear	-1	<u>.</u>		. *

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.