## Nº 5932

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED //- // - 52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	_	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT / 27  CURB LINE AND DEPTH / 27	9 Deep.
WAS LATERAL AT CURBY Yes	ing the state of t	(함 ) 
WAS ATTACHED TO MAIN VES	- NAME OF CONTRACTOR A.J.	DIZNZ
SHOW BY DIAGRAM RELATION OF LAT	FERAL TO WALL OF BUILDING SERVED.	
and one of the company of the state of the	( 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7'C'deys
	The state of the control of the state of the	· 6
₹.V		10 g'del
	3	
SIGNED ALTERY KEE	FILED AT ENGINEER'S OFFIC	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
INSPECTOR FOR C	erre deposit of the first of the first periods	

## Nº 5932

## PERMIT TO TAP SEWER

MASSILLON, OHIO.	[34   374 * 4* 
RECEIVED OF a. 9 Diana FEE	of <b>s</b>
FOR WHICH PERMISSION IS GRANTED Harry 9 Wagne	<u>ال</u>
TO TAP Sanitary SEWER, ON THE YOUTH	
of Marilyon Parker Mave. Type of STREET gravel	i wantan ji Lii
THE PREMISES BEING LOT NO. 1075 3 , HOUSE NO. 150	5
Work to be done in accordance with Ordinance No. 2323, duly passed by the Rules of the Department of Public Service.	CITY COUNC

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.