\mathbf{N}^{o} 5938

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	se-finishmini iliyoni ili ismis osamon sama sama sinasa mentu
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
	ERAL TO WALL OF BUILDING SERVED.
4/	
	<u> 1960 - Televis Indian karrentero de sekis de el el</u>
INSPECTOR FOR C	ELTY LE ALLE ALLE ALLE ALLE ALLE ALLE ALLE

Nº 5938

PERMIT TO TAP SEWER

9 19 19 19 19 19 19 19 19 19 19 19 19 19
RECEIVED OF Samuel Hultin FEE OF 5 2
FOR WHICH PERMISSION IS GRANTED Hamuel Hutting
TOTAP Santand SEWER, ON THE Dart
OF the MAN. AVE. TYPE OF STREETS pared
THE PREMISES BEING LOT NO. 38 49 HOUSE NO. 1532
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Venley!

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.