


Nº 5944

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-2-52IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 609 Lin. Way E.SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 7' 8' clWAS LATERAL AT CURB? NOWAS ATTACHED TO MAIN NONAME OF CONTRACTOR A J Dianna

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

John Ehlers
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-2-53REMARKS: This sewer was tapped.

Nº 5944

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12-5

RECEIVED OF A J Deana FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Baptist Church

TO TAP sanitary SEWER, ON THE south

OF Wallace St AVE., TYPE OF STREET paved

THE PREMISES BEING LOT NO. 1456, HOUSE NO. 609 - Lin

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A J Deana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.