FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 5957 AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-24-	if so how and location from first manhole down stream /38	. /
HOUSE NO. 865	: .	•
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURBY NO	the company of the second of the company of the com	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR Remley	
	LATERAL TO WALL OF BUILDING SERVED.	
	V 26'	21
	7 deys	
^ .	4 dup > 4'1	4
SIGNED John Ed	med FILED AT ENGINEER'S OFFICE 12-27-59	/ —
INSPECTOR	FOR CITY One of year it is provided to the first of the original descriptions.	
REMARKS:	·	

Nº 5957

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, 12-23
RECEIVED OF Ray Romey FEE OF S. 2.
FOR WHICH PERMISSION IS GRANTED TIZED
TO TAP danitary SEWER ON THE
of Cambell Cucle/1 C AVE., TYPE OF STREET paned
THE PREMISES BEING LOT NO. 72 8 4 4 85 , HOUSE NO. 865 860:
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Tenziley

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.