## Nº 5961

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-3-5	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	· ·
HOUSE NO. 29/9	- AND WANTED DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8' L
WAS LATERAL AT CURBI VES		
WAS ATTACHED TO MAIN YES	- NAME OF CONTRACTOR	mey_
The state of the s	ERAL TO WALL OF BUILDING SERVED.	
ilian ila 1970. Bir ilandi bilan di berberakan di perdebagai di bir. Bir ilanggaran di bir		31 Karner
		227
		51 6 9 00
SIGNED John FA	FILED AT ENGINEER'S OFFICE	Ś
INSPECTOR FOR C	de spellere i de l'origine di podribre de cher	

## Nº 5961

## PERMIT TO TAP SEWER

and the control of th
Massillon, Ohio, / 3 3
RECEIVED OF Pan Remby FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED Mis Citie
TO TAP farlay SEWER, ON THE COST
Candlego SA N. 9
OF AVE. TYPE OF STREET AND
ST.
THE PREMISES BEING LOT NO. 10/9 Ce , HOUSE NO. 29/8
$v_{ij}(1)$ $m{\epsilon}$
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Ray Remley

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.