Nº 5962

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-3-5-2	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2208	_
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 270' 9'be
WAS LATERAL AT CURB? Yes	grand Countries of the Research States and S
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR R. R. Memley
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
galanda (h. 1915). An an an an Anna an An anna	
	L'AP
	The section of the constant in the section of the first of the section of the sec
į	
	0
	and the same of th
	13 69 270
SIGNED COMPAN COMP	FILED AT ENGINEER'S OFFICE 12-27-52
INSPECTOR FOR (មាក់ ក្នុង មាននឹងក្រុង ដែល មាន ប្រែសព្ទីក្រុង ប្រជាព្រះសម្រើសនិងសេច និងសេកាក

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE NO. 5962 PERMIT TO TAP SEWER

٠	the same						a ser
		75	norden wer S P kie Ger	MA	ssillon, Ohio,	12-2	3 - 52
	RECEIVED OF	Ray	Pend	Cara .		, <u> </u>	E OF \$ 2
	FOR WHICH PERMISSI	<i>≦)</i> ON IS GRANT	ED	. 90 J	lehale	<u>.</u>	
•	TO TAP Lane	Lan		.SEWER, ON	THE	north	
:	of Duane	Cene	MW AVE	" TYPE OF	STREET C	irt	
	THE PREMISES BEING	LOT NO	602 :	2	, HOUSE NO.	220	8
	WORK TO BE DONE !	N ACCORDAN	CE WITH ORI	DINANCE NO). 2323, DULY P	ASSED BY THE	CITY COUN
	RULES OF THE DEPAR	TMENT OF PU	BLIC SERVICE	<u>.</u>			
	·	α	j)	er)			

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.