

Relay + Repaired

3-6

Nº 5963

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-15-52 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1104


SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 72' 7'

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR R R Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12-27-52

REMARKS: _____

Nº 5963

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12-23-52

RECEIVED OF Ray Remley FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Peter Monte

TO TAP Sanitary SEWER, ON THE north

OF Walnut St AVE., TYPE OF STREET paved
ST.,

THE PREMISES BEING LOT NO. 9455, HOUSE NO. 1104

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.