Nº 5967

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-23-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	381
HOUSE NO. 336		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? // 0		7
WAS ATTACHED TO MAINYES	NAME OF CONTRACTOR	enley
SHOW BY DIAGRAM RELATION OF LATE		
± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ±	to the second of	
		111 de 138
SIGNED INSPECTION SON	FILED AT ENGINEER'S OFFICE_	12-27-524
REMARKS:	i a tibeli jai en rasialga ki jait ilevila elikuus.	· ·

Nº 5967

PERMIT TO TAP SEWER

	MASSILLON, OHIO, 12-23
RECEIVED OF Ray Rember	
District Annual Control of the Contr	4000
FOR WHICH PERMISSION IS GRANTED	the consumer
TO TAPE CANALELY SEWE	R, ON THE COLD
OF 19th St 11C AVE. TYP	e of street <u>filed</u>
THE PREMISES BEING LOT NO. 9145 - 46	2, HOUSE NO
	.i
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN-RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	CE NO. 2323, DULY PASSED BY THE CITY COUNC
R. D.	7
NAME OF CONTRACTOR / Cy	<u>ky</u>

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.