

7/18

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 5965 AND SIGNED WHEN RETURNED.**

DATE INSPECTED 7-28-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1019

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


232' 6' 0

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR R. R. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John Schmeel
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-12-52

REMARKS: _____

Nº 5965

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12-23

RECEIVED OF Ray Remley

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Baptist Temple

TO TAP Sanitary

SEWER, ON THE South

OF Chenook St W

AVE., TYPE OF STREET oiled

THE PREMISES BEING LOT NO. 0 L. 2 & 8

HOUSE NO. 31219

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.