Nº 5969 AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-27-52 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2646 DISTANCE FROM FIRST MANHOLE	,
SIZE OF PIPE USED DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	10
WAS LATERAL AT CURBY YES	
NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
10 pull	
SIGNED FILED AT ENGINEER'S OFFICE 12-27-53	<u> </u>
	HOUSE NO. PIRST MANHOLE DOWN STREAM HOUSE NO. DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH WAS LATERAL AT CURB? WAS ATTACHED TO MAIN VES NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. SIGNED INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE 12-27-53

Nº 5969

PERMIT TO TAP SEWER

	MASSILLON, OHIO, 12-23
	RECEIVED OF Man Permily FEE OF S 2
	FOR WHICH PERMISSION IS GRANTED Pure Oil 2 as 27 ntusin
•	TO TAP SEWER, ON THE Morth
	of In wan have. Type of STREET Paned
•	THE PREMISES BEING LOT NO. PT. OL 174, HOUSE NO. 2476
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC

NAME OF CONTRACTOR Perula

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.