

S.K. 2-9

Nº 5973

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-25-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 413

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

1-8-53

REMARKS:

Went into manhole

D.C.

No. 5973

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/6/53

RECEIVED OF

Ray Remley

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

C.D.O. Hall

TO TAP

Sanitary

SEWER, ON THE

south

OF

Lincoln Way E

AVE.,
ST.,

TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

277

HOUSE NO.

413

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Remley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.