## $\mathbf{N}^{\circ}$ 5980

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 2151	2117		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	10' 8	10
WAS LATERAL AT CURB?		and the second of the Spirit	
WAS ATTACHED TO MAIN	No	a Diama	.* *
	NAME OF CONTRACTORN OF LATERAL TO WALL OF BUILDING SER	RVED.	<u> </u>
	orange in the same of the same		
		The same area of a part of 15 and a same	
		Care	2
マロばび はいばいはい かほう カロメンセン なのきすし			
	<ul> <li>A control of the contro</li></ul>	មាល់ស្រាល់ កាលកាម្មាល់ស្រី 👔 🛂 🗀	
		10'-1/4'dup	
		10'-> / q'dup	THE MET SHEET SHEE

## Nº 5980

## PERMIT TO TAP SEWER

	MASSILLON, OHIO. 16/53
_	RECEIVED OF A A FEE OF S A
H	FOR WHICH PERMISSION IS GRANTED C. E. Akinne
<u> </u>	FOR WHICH PERMISSION IS GRANTED
	TO TAP Santan SEWER ON THE South
	of Clarement not AVE. TYPE OF STREET dist
	THE PREMISES BEING LOT NO. 6045 HOUSE NO. 2+01
	$\alpha/1$
- :	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC
	Rules of the Department of Public Service.

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.