

Relay Job - no new connections.

2-

No 5998

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 1-13-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

69'

9'

HOUSE NO. 107 113

SIZE OF PIPE USED 8"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

R. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Main
Sewer
E. 1st St. N.

26'

8' deep

26' 9' deep

SIGNED

L. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Tapped into Main Sewer.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 5998 PERMIT TO TAP SEWER

MASSILLON, OHIO, 3-17-53 1

RECEIVED OF Ray Remley FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED John Schneider

TO TAP Sanitary SEWER, ON THE west

OF East 11. AVE., TYPE OF STREET low surface
ST.,

THE PREMISES BEING LOT NO. 421, HOUSE NO. 109-113

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.