Nº 6001

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-19-5	IF 50 HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	·
HOUSE NO. 469		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7'06
WAS LATERAL AT CURBY YES	ulius (4) (m. 1992). Pur merek aren en kunkeren bararren kuyarren (h. ⁹⁶). Ma ntanak	7.7
WAS ATTACHED TO MAIN	— NAME OF CONTRACTOR	
	ATERAL TO WALL OF BUILDING SERVED.	
A PARLET A BUTTO IN A TO THE THE PARLET OF THE PARLET.	The second with the second of	
	The second property of the second second to the second of the second sec	
andre Maria (1905) 1980 – Talin Santa (1905)	west & j'deed	3 .
	<u> </u>	
SIGNED + athor	FILED AT ENGINEER'S OFFICE	
REMARKS:	est a dilentifi or resides of paiblied to shave	103

Nº 6001 PERMIT TO TAP SEWER

og program i determination transporter and de program grand program grand program grand program grand program g 	B) #80 97 0 0 3		Massill	ок, Оню,	7 6 - 33
Red	EIVED OF	4 Deca	nd		FEE OF S
۸۶ ـ ۱۳۶۱ پائسیات در سیب	90000 1 <u>mary 1 - 1</u>	erios de recordo. Os os recordos		9.1.11	
FOR WHICH	PERMISSION IS GRAI	NTED		<u>- Wille</u>	an cles
TO TAP	Santary		SEWER, ON THE	une	Tarana
OF	23221	10 AVE	. TYPE OF STREE	a di	7
i da a jira	SES BEING LOT NO.	1.00 mm - 1	and the State of t	17 March 1987 1988 1988	469
				AOOSE NO.	
Work to	BE DONE IN ACCORDA	NCE WITH ORE	INANCE No. 232	23, DULY PASSED	BY THE CITY CO
RULES OF	THE DEPARTMENT OF F	PUBLIC SERVICE			

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.