

N^o 6024

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-30-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1818

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 43'



8' DEEP

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Beaver

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED J. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

5-99

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
 No. 6024 PERMIT TO TAP SEWER

MASSILLON, OHIO, April 29 1918

RECEIVED OF Beaver Construction Co. FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED Jacob Hlick

TO TAP Sanitary SEWER, ON THE north

OF Stone St NE AVE., TYPE OF STREET dirt
 ST.,

THE PREMISES BEING LOT NO. 8122, HOUSE NO. 1818

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beaver Construction Co.

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.