## Nº 6057

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED		OW AND LOCATION FROM	, te		:
HOUSE NO.	1003	MANHOLE DOWN STREAM		:	
SIZE OF PIPE USED	/ U (-bown	CE FROM FIRST MANHOLE STREAM TO DITCH AT INE AND DEPTH	117'	12 Stream	MS/3/00
WAS LATERAL AT CL	JRB1 YES	ing na manggalang ang kalang ang Kalanggalang	e traen. Tak decembră Tak		
WAS ATTACHED TO	MAINNAME	OF CONTRACTOR	Willen	12 X Rus	alex
SHOW BY DIAGRAM	RELATION OF LATERAL TO	WALL OF BUILDING SE	ERVED.	1	0
			eronom kaja en <u>Estimat</u> Pi	13/00	Cerp
engage <sup>ter</sup> en la jar als esplese	The state of West	en same and an and an	Venezasi izledi ni kultara speriji. Ni da izledi izledi izledi izledi.	5/2	
				10	-61/2 Cust
			Ψ		The second secon
SIGNED	INSPECTOR FOR CITY	FILED AT EN	IGINEER'S OFFICE		
REMARKS:			ARRANDED LEV CRADOVE RANG		

## Nº 6057

## PERMIT TO TAP SEWER

and the second s	Massillon, Ohio,
RECEIVED OF	Mulbal FEE OF SO
FOR WHICH PERMISSION IS GRANT	
TO TAP	SEWER, ON THE
of 15th All	AVE., TYPE OF STREET
THE PREMISES BEING LOT NO.	£ 276 , HOUSE NO. 1003
	E WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUR

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNC. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR When I Kingley

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.