Nº 6068

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

| DATE INSPECTED 5-20-53 IF SO HOW AND I | |
|--|---|
| HOUSE NO. 843 | DOWN STREAM |
| SIZE OF PIPE USED 6 CURB LINE AND I | DITCH AT $09'$ |
| WAS LATERAL AT CURB? YES | or one realized desired these desired |
| WAS ATTACHED TO MAIN NAME OF CON | FRACTOR a a a a a a a a a a a a a a a a a a a |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF | BUILDING SERVED. |
| | 27' |
| | / caux |
| | |
| | 131/7 duy upstr |
| CAY 4 Th | 29'0 |
| SIGNED INSPECTOR FOR CITY | FILED AT ENGINEER'S OFFICE |
| REMARKS: | |

5-53/6/

Nº 6068

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | MASSILLON, OHIO, 6/9/53 |
|---|--|
| | RECEIVED OF A CONC. FEE OF 5 |
| ۶ | FOR WHICH PERMISSION IS GRANTED FLOYA A. Dawyen |
| | TO TAP SUNITARY SEWER, ON THE SOUTA |
| | of Tranklin Rah & Type of STREET oiled |
| | THE PREMISES BEING LOT NO. 7033 , HOUSE NO. 743 |
| | WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC |

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC.

IAME OF CONTRACTOR A Juana

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.