

7-2

Nº 6070

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-20-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1227

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

36'



7'd

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Urban & Ringle

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Leroy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

7-72

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 6070 PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/19, 1976
RECEIVED OF Verlan + Ringley FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Tred Bohman
TO TAP San SEWER, ON THE 111
OF Andrew AVE., TYPE OF STREET Hard surf
THE PREMISES BEING LOT NO. 1376, HOUSE NO. 1222

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Verlan + Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.