4-23

Nº 6081

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

and the control of th
DATE INSPECTED 10-1-53 IF SO HOW AND LOCATION FROM 12000 365 11.5
House No. 203-28 (e
DISTANCE FROM FIRST MANHOLE 39 30 00000
SIZE OF PIPE USED DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB7
WAS ATTACHED TO MAIN 188 NAME OF CONTRACTOR Moon & Pringely
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
Figure 6 No. 1 Commence William Commence of the Commence of th
SIGNED MON TO FILED AT ENGINEER'S DEFICE AND
inspector for City and a residue in yord to slight to slight
REMARKS:

4-26-29

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

1	PERMIT TO TAP SEWER
Lown Plazo	Massillan Outs $8/11/53$
10 - O. O.	MASSILLON, OHIO,
Hollin Chile	RECEIVED OF THE OF SA FEE OF SA
	FOR WHICH PERMISSION IS GRANTED RIGHT PARTY AND
	TO TAP Canday SEWER ON THE last
	of 3rd 11 ml AVE. TYPE OF STREET hard surfac
	THE PREMISES BEING LOT NO PHODE NO. 202 - 286
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit cover's work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.