## Nº 6093

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

<i>A</i>	
DATE INSPECTED 9-17-5-3	IF SO HOW AND LOCATION FROM
HOUSE NO. 226	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 3/
WAS LATERAL AT CURBI	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	1 / Colup
Garage Control of the Control	en la reconsidera de la compacta de
	and the second of the control of the control of the second
1	$I_{1}$
	1 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2
	The state of the s
SIGNED	FILED AT ENGINEER SOFFICE   2-2  -53
INSPECTOR FOR CIT	
REMARKS: The Mt. Was built lan	tel and is 31th from My instead of 439' last of ear

curbline of 1 th St. 72.

## Nº 6093

## PERMIT TO TAP SEWER

	MASSILLON, OHIO. 9/16/	54 15
RECEIVED OF 11-August	Suger FE	E of \$2 "
FOR WHICH PERMISSION IS GRANTED	e 3 Amit	
TO TAP Cantany SEWER	ON THE MON	til
	of Street	24
THE PREMISES BEING LOT NO. 5528	HOUSE NO.	6

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR / JAVam Wir G.

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.