## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6120 AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-17-5 3 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO
SIZE OF PIPE USED 6 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 129 CURB LINE AND DEPTH
WAS LATERAL AT CURBY Yes
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR When & Rengeley
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
7.5 dup
133 C'del
V 129'
SIGNED MAY WAR FILED AT ENGINEER'S OFFICE /// -
INSPECTOR FOR CITY
DEMARKS.

### 6-33

#### Nº 6120

# PERMIT TO TAP SEWER

	Massillon, Ohio, Coc	1 16 - 1773 15
RECEIVED OF Chlan & Re	ngly	FEE OF \$
FOR WHICH PERMISSION IS GRANTED Liban	1 Remale 1	- Remell M.
9 -	J. F.	
TO TAP SOME SEWER		<u>arkanda historikan ing Meriling.</u> Sanggarangkan
OF 11th LAME AVE. TYPE	OF STREET ROUNT	surface
THE PREMISES BEING LOT NO. 8324 7 25	. HOUSE NO	422

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Cloban & Kingly

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.