Relaid 1-16

## TANKET OF THE STATE OF THE STAT AND SIGNED WHEN RETURNED.

DATE INSPECTED $9-19-5$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. /27		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  OP DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	7.5 12841
WAS LATERAL AT CURB?	<u>angan da tan dinggin dan kanana da Matana da kanang bahasan da tan</u>	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Rembus
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERVED.	1.5 dell
A		
	and the state of the	
	10stream	1 Jest
	01/4	1 23' \ 7.3
SIGNED XLON ACTION OF THE INSPECTOR FOR CO.	FILED AT ENGINEER'S OFFICE	111-
Predeficio Maria de Combreso. PREMARKS:	The methodality of a coldan of the boldes for all and of	1-103

### 1-10

# Nº 6125

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO. 1/-6-53 15
RECEIVED OF Ray Rem	luy) FEE OF S
	<u>All de de de de la companya de la c</u>
FOR WHICH PERMISSION IS GRANTED	<u>alo</u>
TO TAP SONITARY SEWER	ON THE
of Jouth September AVE. TYPE	OF STREET buck
THE PREMISES BEING LOT NO. 9 60 3	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	NO. 2323, DULY PASSED BY THE CITY COUNC

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.