

9-8

Nº 6126

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-18-53

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM (stack) 6' A

HOUSE NO. 2722

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. R. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Leroy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11/23/53

REMARKS: _____

46-9-10-1

NO 6126

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11-6-53 11

RECEIVED OF Ray Remley FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED George Hendley

TO TAP Sanitary SEWER, ON THE N.

OF Lincoln NW AVE., TYPE OF STREET Hard

THE PREMISES BEING LOT NO. 10190, HOUSE NO. 2722

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.