FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 6162 AND SIGNED WHEN RETURNED.

DATE INSPECTED 1-28-54 HOUSE NO. 942	IF SO HOW AND LOCATION FROM 25 / 7 / Deg
SIZE OF PIPE USED 611 WAS LATERAL AT CURB? NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Premier
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	9' 25'
REMARKS:	FILED AT ENGINEER'S OFFICE 2-20-54

Nº 6162

PERMIT TO TAP SEWER

en e	1. Lorenton
	MASSILLON, OHIO,
RECEIVED OF RAMMER at	Remles FEE OF 52
FOR WHICH PERMISSION IS GRANTED	l Yeth
TO TAP Sanitan SEWE	R, ON THE Land
OF 322011 MA AVE., TY	e of Street rold
THE PREMISES BEING LOT NO.	942 HOUSE NO. 942

Work to be done in accordance with Ordinance No. 2323, Duly Passed by the City Counci Rules of the Department of Public Service.

NAME OF CONTRACTOR Many

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.