



Nº 6167

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 2-19-54IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 100SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 120' 4' DeepWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN NONAME OF CONTRACTOR Unborn & Ringler

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-20-54

REMARKS: _____

Nº 6167

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2-18 1915

RECEIVED OF Urban and Ringley FEE OF \$ 5.00
George

FOR WHICH PERMISSION IS GRANTED George

TO TAP sanitary SEWER, ON THE east

OF 15th n.w AVE., TYPE OF STREET Local
ST.,

THE PREMISES BEING LOT NO. 8659, HOUSE NO. 1.00

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Urban and Ringley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.