## Nº 6176

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-		O HOW AND LOCATION FRO		
HOUSE NO/38	// Dis-	FANCE FROM FIRST MANHOL	LE 158?	-
SIZE OF PIPE USED $\qquad \qquad \qquad$	(2 /	STREAM TO DITCH AT	185' UP Stream	7'0,
WAS LATERAL AT CURB?	NO NA	ME OF CONTRACTOR _	Milant	Mindey
SHOW BY DIAGRAM RELAT	ION OF LATERAL	TO WALL OF BUILDING	SERVED.	
			A Committee of the comm	_8.
	N	7 (1)	The Committee of the Co	Colaro
			. V d f lina i individual Sili. I	3
			158	2 12dees
SIGNED SEAVY	La de la companya della companya della companya de la companya della companya del	FII FD AT	ENGINEER'S OFFICE	2 15
REMARKS:	ECTOR FOR CITY	(genis en trekere)	_	3-07-0

## Nº 6176

## PERMIT TO TAP SEWER

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
RECEIVED OF Urban & Ringley
FOR WHICH PERMISSION IS, GRANTED Roman 3 wich
TO TAP SUNCTON SEWER, ON THE SANT
of 27 Il le AVE. TYPE OF STREET Oil a
THE PREMISES BEING LOT NO. 6892 HOUSE NO. 138
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Itoban & Cling ley

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.