

5-40

Nº 6188

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-21-54

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1784

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

38'


7' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR Urban & Ringley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

L. H. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 6188

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

4-21-54 19

RECEIVED OF

Urban & Riegley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Harland Mauer

TO TAP

San

SEWER, ON THE

N.

OF

Jefferson N E

AVE.
ST.

TYPE OF STREET

Alled

THE PREMISES BEING LOT NO.

8088

HOUSE NO.

1734

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Urban & Riegley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.