

9-25
9-23

Nº 6200

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-4-54 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 461

SIZE OF PIPE USED 6" UP DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 133' UPSTREAM 8' deep
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No NAME OF CONTRACTOR Urban & Ringler

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 6200

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/1 1915

RECEIVED OF Urban & Rungley

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED John ~~W. H. H.~~ Ohlman

TO TAP San

SEWER, ON THE west

OF 3rd Ave

AVE.
ST.

TYPE OF STREET paved

THE PREMISES BEING LOT NO. 7368

HOUSE NO. 461

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Urban & Rungley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.